




Repair instruction

Description: C2 C3 C4 (produced after 15 June 2000) Lip seal
Part number: 23721
 Look for Service Centers, Point of Sale addresses and other information on: www.thetford-europe.com

Version:	V2
Date:	13/07/2006
Tools required:	

A

Remove the sliding Cover.





B

Place new lip seal on the waste tank.
Note: Thinner flange has to face downwards towards the blade.



C

Screw the seal cover back onto the waste tank.



Place sliding cover back on its place. Make sure that the two arrows are pointed to each other.